From: Scott Quinlan [s.quinlan@gaiconsultants.com]

Sent: 6/24/2015 10:09:45 AM

To: Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]

CC: Amelia H Boschen (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Amelia2]; Michael A Glagola (Generation - 34)

[/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Mic0210];

Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeff136]; John Klamut [J.Klamut@gaiconsultants.com]; John DeBarbieri

[J.DeBarbieri@gaiconsultants.com]

Subject: Revised Sampling Data

Attachments: Pond Closure Quality-Flows-Schedule.docx

Ken:

Attached are the Quality-Flows-Schedule information and the treatment/handling options for the various wastewaters incorporating the lab test results to date.

There are some items to note in the three (3) Pond D surface water samples collected this month:

- TSS levels appear to have been lowered to acceptable levels (i.e., < 30-ppm Outfall 005 limit) since our original May 2015 sample.
- Dissolved selenium levels have increased noticeably since our original May 2015 sample. Dissolved selenium may now be of concern. We have means of polishing this if needed.
- Temperature readings on 2 of the 3 recent Pond D samples exceeded the PWCSA limit (30-deg C).
 The remaining sample is practically at the limit. We do not anticipate this to be a problem in operation, based upon where the pumps will be drawing water. The samples were taken near a shallow location, where radiant heat elevates the water temperature at the surface.
- The other parameters appear to be in compliance with PWCSA limits.

There are a few items to note for the Low Volume Waste Settling Ponds samples collected this month (north and south ponds/cells):

The field measurement for pH at the south pond/cell was high.

- pH went up from the north to the south pond/cell.
- The dissolved copper levels were low enough to be undetected. We may be able to blend the LVWP waters with the Oily Wastewater to meet the 5-ug/L limit, depending on the flows.

Please forward as appropriate. Let me know if you have any questions. Thanks.

Sincerely,

Scott C. Quinlan, PE

Director - Energy Water Resources Engineering and Planning

GAI Consultants, Inc.

500 Cranberry Woods Drive, Cranberry Township, PA 16066

724.772.2011 ext. 2409 | C 412.584.4508 | **f y in a e Brochures**

fransforming ideas into reality_® since 1958 | gaiconsultants.com

CONFIDENTIALITY NOTICE: This communication contains confidential information belonging to the sender and may be legally privileged. This communication is solely for the use of its intended recipient. If you are not the intended recipient, inform the sender of the error and remove this email from your system. If this transmission includes any technical information, design data, and/or recommendations, they are provided only as a matter of convenience and may not be used for final design and/or construction.